



正本



SDZZ/HT-2021-DV1376

检测报告

Testing Report

山中检字(2021)第DY1376-BN2号

项目名称: 半年度检测项目(无组织废气、废水)

委托单位: 东营神驰仓储有限公司

A 3D visualization of a 10x10x10 grid of voxels, colored by density. The grid is divided into three vertical sections. The left section (x=0-3) shows a solid blue block. The middle section (x=4-6) shows a solid red block. The right section (x=7-9) shows a solid green block. The top surface of the grid is marked with a grid of small blue and red dots, indicating specific data points or features.

[illegible]

項目	内容	備考
1. 調査の目的	本調査は、〇〇市の人口動態を把握し、今後の政策立案に資することを目的とする。	
2. 調査の範囲	〇〇市全域を対象とし、調査期間は平成〇〇年〇月〇日から〇月〇日までとする。	
3. 調査の方法	戸別訪問調査と電話調査とを併用し、調査結果の信頼性を高める。	
4. 調査の結果	調査結果は、〇〇市の人口は〇〇人であり、年齢構成は〇〇歳代が最も多いことが確認された。	
5. 調査のまとめ	本調査の結果、〇〇市の人口動態は概観でき、今後の政策立案に役立つと判断される。	

检测 报 告

山中检字（2021）第 DY1376-BN2 号

2.3 无组织废气检测结果

2.3.1 厂界无组织废气

采样点	采样时间	采样位置	采样高度	采样流量	采样体积	采样结果
1	2021.08.10 08:00	厂界上风向	1.5m	10L/min	10L	0.01mg/m ³
2	2021.08.10 08:00	厂界下风向	1.5m	10L/min	10L	0.01mg/m ³
3	2021.08.10 08:00	厂界上风向	1.5m	10L/min	10L	0.01mg/m ³
4	2021.08.10 08:00	厂界下风向	1.5m	10L/min	10L	0.01mg/m ³

18

181

182

183

采样点	采样时间	采样位置	采样高度	采样流量	采样体积	采样结果
1	2021.08.10 08:00	厂界上风向	1.5m	10L/min	10L	0.01mg/m ³
2	2021.08.10 08:00	厂界下风向	1.5m	10L/min	10L	0.01mg/m ³
3	2021.08.10 08:00	厂界上风向	1.5m	10L/min	10L	0.01mg/m ³
4	2021.08.10 08:00	厂界下风向	1.5m	10L/min	10L	0.01mg/m ³

184

185

186



ZHONGYUAN

SDZ77ZLJL-029-4

ZHONGYUAN

检测报告

72 号

第 4 页 共 5 页

山中市环字(2021)第 DY1376-B

2.4 废水检测结果

表 6 废

水检测结果一览表

采样日期: 2022.06.16

单位	采样频次及检测结果		
	1	2	3
无量纲	7.4	7.4	7.3

采样点位	检测项目
废水	pH



ZHONG ZE

检测报告

SDZZ/ZLJL-029-4

山中检字(2021)第DY1376-BN2号

第 1 页 共 1 页

报告说明

- 1.报告无本公司检验检测专用章、骑缝章无效。
- 2.报告无编制人、审核人、授权签字人签名无效。

3. 报告涂改、错页、

提供的样品及有关信息的真实性负责。

7.对检测报告若有异议，应于收报告之日起十五日内向本公司提出，逾期不予受理。

8. 加盖CMA章的检验检测报告, 其数据、结果具有证明效力; 不加盖CMA章的检验检测报告, 仅供委托方内部科研、教学、交流、参考。